

Plastic spare key for small MCP



Part-No.: 704966

With this plastic service key the housing is push opened to replace the glass pane and the test functionality of the manual call point is activated and reset.

Common technical data